

Work Order ID 53508

November 6, 2009 4:08:55 PM

Page 1

Item ID: D119-646-311

Accept

Revision ID: B

Item Name: Ground Handling

Start Date: 06/11/2009 Start Qty: 1.00

Required Date: 13/11/2009 Req'd Qty: 1.00

Reference:

Approvals: Process Plan: PL Date: 09-11-9

QC: _____ Date: _____ SPC (Y/N): _____

Cust Item ID:

Customer:

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D119-646	B								

100

0.00



DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP D119-646-311
CHG001

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

9/12/11 SKH

1 PS-12-22

Work Order ID 53508

November 6, 2009 4:08:55 PM



Page 2

Item ID: D119-646-311

Accept



Setup Start



Revision ID: B

Stop



Item Name: Ground Handling

Start Date: 06/11/2009 Start Qty: 1.00



Cust Item ID:

Required Date: 13/11/2009 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D119-646-311								
	Location: <u>A</u>								
	PPP rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.00							
Quality Control									

C209112123

Picklist Print

November 6, 2009 4:08:58 PM

Page 1 1/2

Work Order ID: 53508

Parent Item: D119-646-311RevB

Parent Item Name: Ground Handling

Comments:

Start Date: 06/11/2009

Required Date: 13/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3886-041RevB		Manufactured	No			110	Each	0.0000	2.0000	②		
Lug Assembly												
D2652RevA		Manufactured	No			110	Each	580.0000	8.0000			
Bushing												

B53920 9/12/00 sf

9/12/11 sf

Warehouse Loc Qty Loc Code

Location

OFFSHORE

FG 44

31985 44

Main Warehouse

ST40 536

51531 536

110 Each 79.0000 4.0000

8x

9/12/11 sf (K)

AN3C46A

BOLT

Purchased No

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST 79

106169 5

106176 9

11918 65

9x

Picklist Print

November 6, 2009 4:08:58 PM

Work Order ID: 53508

Parent Item: D119-646-311RevB

Parent Item Name: Ground Handling

Comments:

Start Date: 06/11/2009

Required Date: 13/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

AN960C10L

Purchased

No

110

Each

3,906.000

4.0000



washer



9/12/11 SL

Warehouse

Loc Qty

Loc Code

Location

OFFSHORE

FG

100

103585

100

Main Warehouse

ST

3806

112116

628

112612

2178

112933

1000

MS21043-4

Purchased

No

110

Each

1,440.000

4.0000



Nut



9/12/11 SD (12)

Warehouse

Loc Qty

Loc Code

Location

OFFSHORE

FG

40

104603

40

Main Warehouse

ST

1400

112243

2

112314

598

112492

300

113064

500

Work Order ID 53508

November 6, 2009 4:08:55 PM



Item ID: D119-646-311

Accept



Setup Start



Revision ID: B

Stop



Item Name: Ground Handling

Start Date: 06/11/2009 Start Qty: 1.00



Cust Item ID:

Required Date: 13/11/2009 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals:

Process Plan:

Date: 02-11-09

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

IIN-D119-646

B

100

0.00



DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP D119-646-311
CHG001

09-12-11

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

REFERENCE ONLY

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control